

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340

RECEIVED
MAR 22 1989

DIVISION OF
OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/88 To (mo./yr.) 1/89
2. DOGM File Number (original notice): S / 017 / 022
3. Mine Name: Project 36 (T.31S., R.10E., Sec. 36 N/2N/2, Garfield Co.)
4. Mineral(s) Mined: Placer Gold
5. Name of Operator or Company: Crescent Creek Mining Company
6. Permanent Address: 3901 Indian School Rd. NE #307D
Albuquerque, NM 87110
7. Company Representative (or designated operator):
Name: Richard J. Claus
Title: Owner
Address: 3901 Indian School Rd. NE #307D
Phone: Albuquerque, NM 87110

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? One 3-cubic yard sample was taken and treated from a 50-cubic yard excavation.

3. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected. With reference to the plan submitted August 1, 1988, only one sample site was excavated. The exploration trench measured about 2.5 yds. wide, 5 yds. long and 4 yds. deep equivalent to 50 cu. yds.
The surface disturbance was +0.25% of an acre; the test hole was backfilled and tamped by dozer.
4. Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results.
Except for the above described test hole, no other surface disturbance occurred during 1988. The hole was dug in an exempt locale; the existing surface consisted of alluvial sand, gravel and cobbles.
5. What was the total unreclaimed acreage at years end? None
6. Briefly summarize mining and reclamation planned for the upcoming year.
As yet to be decided.


NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Signature of Operator: 
Name (Typed or Print): RICHARD J. CLAU
Title of Operator: OWNER
Date: March 20, 1989